Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	84284	interruptor breaker	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 10:01
L2	271131	"335"/\$.ccls. "200"/\$.ccls. "174"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 10:59
L3	4577242	open off disengaged	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 09:51
L4	3060236	install\$5 distribut\$5 sold maintanence	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 09:58
L5	3060415	install\$5 distribut\$5 sold maintanence	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 09:50
L6	3060415	install\$5 distribut\$5 sold maintanence	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 09:51
L7	4708198	open off disengaged trip\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF ·	2005/08/07 10:02
L8	349720	7 with contact	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 10:00
L9	413587	7 with contact	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 09:52
L10	3060415	install\$5 distribut\$5 sold maintanence	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 09:56

L11	12583	10 and 9 and 2	US-PGPUB; USPAT;	OR	ON	2005/08/07 09:56
			USOCR; EPO; JPO; IBM_TDB			
L12	3060415	install\$5 distribut\$5 sold maintanence	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 09:56
L13	38314	12 same 9	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 09:57
L14	4795	12 same 9 and 2	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 09:57
L15	3300498	install\$5 distribut\$5 sold maintenance	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 09:59
L16	3300730	install\$5 distribut\$5 sold maintenance	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 10:20
L17	120004	7 near2 (contacts contact)	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 10:20
L18	93860	interruptor breaker	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 10:01
L19	676	15 same 17 and 18 and 2	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 10:04
L20	4581869	open off disengaged tripped	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 10:02

L21	116276	20 near2 (contacts contact)	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 10:03
L22	3013	15 same 20 and 18 and 2	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 10:04
L23	2204	15 same "22" and 18 and 2	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 10:04
L24	594	15 same 21 and 18 and 2	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 10:12
L25	110	15 with 21 and 18 and 2	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 10:58
L26	3334467	install\$5 distribut\$5 sold maintenance shipped	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 10:20
L27	23418	26 near2 (contacts contact)	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 10:20
L28	0	26 with 21 and 18 and 2 not 25	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON .	2005/08/07 10:21
L29	9	("3590180" "4152683" "4622530" "4701733" "4724411" "5369384" "5508670" "Re34396").PN. OR ("5719363"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/08/07 10:28
L30	45716	gfci gfi ground adj fault over adj current overcurrent	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:18

L31	20736	26 and 30	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 10:30
L32	142	26 with 21 and 30	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 10:30
L33	5432	installation and 30	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:02
L34	387856	"335"/\$.ccls. "200"/\$.ccls. "174"/\$.ccls. "361"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 13:13
L35	1773	33 and 34	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:03
L36	36331	installation and reset	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:02
L37	1828	installation and reset and 30	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:18
L38	761	37 and 34	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:03
L39	45716	gfci gfi ground adj fault over adj current overcurrent	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:18
L40	180	installation same reset and 39	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:18

	444	installation or a second of the second of th	LIC DODUB	00	ONI	2005/00/07 44-24
L41	114	installation same reset and 39 and 34	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:21
L42	80	installation same reset same 7 and 39 and 34	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:21
L43	197	install\$5 same reset same 7 and 39 and 34	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 11:53
L44	31	"6,246,558"	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 13:12
L45	3957	test\$3 same 7 and 30	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 13:14
L46	488909	"335"/\$.ccls. "200"/\$.ccls. "174"/\$.ccls. "361"/\$.ccls. "327"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 13:14
L47	1285	45 and 46	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2005/08/07 13:14
L48	684	test\$3 same 7 same 26 and 30	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 13:16
L49	118	installed same 21 and 39	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 13:25
L50	6	factory with test\$3 with 7 and 39	US-PGPU B; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 13:35

			· · · · · · · · · · · · · · · · · · ·		1	
L51	0	39 and shipped with 21	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 13:35
L52	21	39 and installed with 21	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 13:37
L53	142	39 and 26 with 21	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 13:45
L54	0	pretripped and 39	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 13:45
L55	90	before near3 tripped and 39	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2005/08/07 13:45
L56	14	("4034266" "4595894" "4719437" "4802052" "4851951" "4967308" "5223810" "5224006" "5594398" "5600524" "5805397" "6040967" "6246558").PN. OR ("6693779"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/08/07 13:52
L57	37	reset near4 installed and 39	US-PGPU B; USPAT; USOCR	OR	ON	2005/08/07 13:52